

QDot™ perovskite X-ray scintillator

SAFETY DATA SHEET

according to OSHA HCS Hazcom 2012, Version 2.0 Revised Date 14/05/2022

SECTION 1: Identification

1.1 Product identifiers

Product name: QDotTM perovskite X-ray scintillator
Product number: QDotTM perovskite X-ray scintillator

1.2. Relevant identified uses of the substance or mixture and uses advised against

Identified uses: Scientific research and development

1.3. Details of the supplier of the safety data sheet

Company: QUANTUM SOLUTIONS

Unit 8, Innovation Quarter, Oxford

Technology Park, OX5 1RD, Oxford, United

Kingdom

www.quantum-solutions.com info@quantum-solutions.com

Phone +44 7389826941

1.4 Emergency telephone number

Emergency phone: +44 7389826941 (Monday to Friday 08:00 to

18:00 GMT)

Emergency Action: In the event of a medical enquiry involving this

product, please contact your doctor or local hospital accident or emergency department

and show this SDS.

SECTION 2 Hazards identification

2.1. Classification of the substance or mixture (GHS Classification in accordance with 29 CFR 1910 (OSHA HCS):

Acute Tox. 4, Acute oral toxicity (Category 4), H302

Skin Irrit. 2, Skin Corrosion/Irritation (Category 2), H315

Skin Sens. 1A, Skin Sensitization (Category 1 Sub-category 1A), H317



QDot™ perovskite X-ray scintillator

Eye Dam. 1, Serious Eye Damage/Eye Irritation (Category 1), H318

Repr. 2, Reproductive Toxicity (Category 2), H361

STOT RE 1, Specific target organ toxicity - (repeated exposure) (Category 1), H372

Aquatic Acute 1, Acute aquatic toxicity (Category 1), H400

Aquatic Chronic 2, Chronic aquatic toxicity (Category 2), H411

2.2. GHS Label elements, including precautionary statements:



- Signal word: Danger

Hazard statements

H302 - Harmful if swallowed

H315 - Causes skin irritation

H317 - May cause an allergic skin reaction

H318 - Causes serious eye damage

H361 - Suspected of damaging fertility or the unborn child

H372 - Causes damage to organs through prolonged or repeated exposure

H400 - Very toxic to aquatic life

H411 - Toxic to aquatic life with long lasting effects

Precautionary statements

P201 - Obtain special instructions before use

P260 - Do not breathe dust/fume/gas/mist/vapors/spray

P273 - Avoid release to the environment

P280 - Wear protective gloves/protective clothing/eye protection/face protection



QDot™ perovskite X-ray scintillator

P301 + P330 + P331 - IF SWALLOWED: rinse mouth. Do NOT induce vomiting

P302 + P352 - IF ON SKIN: Wash with plenty of soap and water

P308 + P313 - IF exposed or concerned: Get medical advice/attention

P332 + P313 - If skin irritation occurs: Get medical advice/attention

P305 + P351 + P338 - IF IN EYES: Rinse cautiously with water for several minutes.

Remove contact lenses, if present andeasy to do. Continue rinsing

P310 - Immediately call a POISON CENTER or doctor/physician

P280 - Wear protective gloves/protective clothing/eye protection/face protection

2.3. Hazards not otherwise classified (HNOC) or not covered by GHS

None

SECTION 3 Composition/Information on ingredients

3.1. Substances:

Ingredients	Classification	Concentration
Perovskite material (trade secret)	Acute Tox. 4 (H302), Skin Irrit.	100 %
	2 (H315), Skin Sens. 1A (H317),	
	Eye Dam. 1 (H318), Repr. 2	
	(H361), STOT RE 1 (H372),	
	Aquatic Acute 1 (H400),	
	Aquatic Chronic 2 (H411)	

SECTION 4 First-aid measures

4.1. Description of first aid measures

General advice	Immediately remove any clothing soiled by the product. Consult a doctor.
After inhalation	Supply fresh air. If required, provide artificial respiration. Consult a doctor.
After skin contact	Immediately rinse with water and wash skin with soap. Consult a doctor.
After eye contact	Rinse opened eye for several minutes under running water. Consult a doctor.
After swallowing	Rinse mouth with water. Do not induce vomiting. Immediately call a doctor.



QDot™ perovskite X-ray scintillator

4.2. Most important symptoms and effects, both acute and delayed

The most important known symptoms and effects are described in the labelling (see section 2.2) and/or in section 11

4.3. Indication of any immediate medical attention and special treatment needed

No data available

SECTION 5 Fire-fighting measures

5.1 Extinguishing media

Suitable extinguishing media

Use water spray, alcohol-resistant foam, dry chemical

or carbon dioxide

5.2. Special hazards arising from the substance or mixture

No

5.3. Advice for firefighters

Firefighting instructions Cool tanks/drums with water spray/remove them into

safety. Do not move the load if exposed to heat

Protection during firefighting Use respiratory protective device compressed or

air/oxygen apparatus

SECTION 6 Accidental release measures

6.1. Personal precautions, protective equipment and emergency procedures:

Use personal protective equipment. Avoid breathing vapors, mist or gas. Ensure adequate ventilation. Remove all sources of ignition.

6.2. Environmental precautions

Prevent further leakage or spillage if safe to do so. Do not let product enter drains. Discharge into the environment must be avoided.

6.3. Methods and material for containment and cleaning up

Contain spillage and then with an electrically protected vacuum cleaner or by wet-brushing or absorb with liquid-binding material (sand, diatomite, acid binders, universal binders, sawdust) and place in container for disposal according to local regulations.

SECTION 7 Handling and storage



QDot™ perovskite X-ray scintillator

7.1. Precautions for safe handling

Avoid eye and skin contact. Avoid inhalation of vapour or mist. Keep away from sources of ignition. No smoking. Take measures to prevent the build up of electrostatic charge. Keep respiratory protective device available.

7.2. Conditions for safe storage, including any incompatibilities

Storage: Keep container tightly closed in a dry and well-ventilated place

7.3. Specific end use(s)

Apart from the uses mentioned in section 1.2 no other specific uses are stipulated

SECTION 8 Exposure controls/personal protection

8.1. Control parameters

Components with workplace control parameters

8.2. Exposure controls

under appropriate government standards such as

NIOSH (US) or CEN (EU)

Hand protection The selected protective gloves have to satisfy the

specification of EU Directive 89/686/EEC and the standard EN 374 derived from it. Handle with gloves.

Eye protection Safety glasses with side-shields conforming to NIOSH

(US) or EN166 (EU)

Skin and body protection Choose body protection according to the amount and

concentration of the dangerous substance at the work place. Handle with gloves. Wash and dry hands. The

selected protective gloves have to satisfy the specifications of EU Directive 89/686/EEC and

standard EN 374 derived from it

Hygiene measures Handle in accordance with good industrial hygiene

and safety practice. Wash hands before breaks and at

the end of workday

SECTION 9 Physical and chemical properties

9.1. Information on basic physical and chemical properties

Appearance Form: Solid

Colour: White



QDot™ perovskite X-ray scintillator

No data available
No data available
No data available

9.2 Other information

No data available

SECTION 10 Stability and reactivity

10.1. Reactivity

No data available

10.2. Chemical stability

Stable under recommended storage conditions

10.3. Possibility of hazardous reactions

No data available

10.4. Conditions to avoid



QDot™ perovskite X-ray scintillator

No data available

10.5. Incompatible materials

Strong oxidizing agents

10.6. Hazardous decomposition products:

No data available.

SECTION 11 Toxicological information

11.1. Information on toxicological effects

Acute toxicity

Irritation

No data available

Corrosivity

No data available

Sensitisation

No data available

Repeated dose toxicity Specific target organ toxicity - repeated exposure (Category 1)

Carcinogenicity No data available
Mutagenicity No data available
Toxicity for No data available
reproduction

SECTION 12 Ecological information

12.1. Toxicity

Acute aquatic toxicity (Category 1)

Chronic aquatic toxicity (Category 2)

12.2. Persistence and degradability

No data available

12.3. Bioaccumulative potential

No data available

12.4. Mobility in soil

No data available



QDot™ perovskite X-ray scintillator

12.5. Results of PBT and vPvB assessment

No data available

12.6. Other adverse effects

No data available

SECTION 13 Disposal considerations

13.1. Waste treatment methods

Must not be disposed of together with household garbage. Do not allow product to reach sewage system. Observe all federal, state, and local environmental regulations. Contact a licensed professional

SECTION 14 Transport information

14.1. UN number DOT: 3077

IMDG: 3077 IATA: 3077

14.2 UN proper shipping name DOT: Environmentally hazardous substances, solid,

n.o.s

IMDG: Environmentally hazardous substances,

solid, n.o.s

IATA: Environmentally hazardous substances, solid,

n.o.s

14.3 Transport hazard class(es) DOT: 9

IMDG: 9 IATA: 9

14.4 Packing group DOT: III

IMDG: III IATA: III

14.5 Environmental hazards DOT: Yes

IMDG marine pollutant: Yes

IATA: Yes

14.6 Special precautions for userNo data available

14.7 Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code

Not applicable



QDot™ perovskite X-ray scintillator

SECTION 15 Regulatory information

15.1. Safety, health and environmental regulations/legislation specific for the substance or mixture

No data available

15.2. Chemical safety assessment

No data available

SECTION 16 Other information

This information is based on our present knowledge. However, this shall not constitute a guarantee for any specific product features and shall not establish a legally valid contractual relationship.

Preparation Information:

Version 3.0

Revised date: 17/11/2024



QUANTUM SOLUTIONS

Address: Unit 8, Innovation Quarter, Oxford Technology Park, OX5

1RD, Oxford, United Kingdom
Web: www.quantum-solutions.com
E-mail: info@quantum-solutions.com

Tel.: +44 73 89826941